PROCESS FOR THE PREPARATION OF UREA GRANULES

PCT/EP2004/011678

5

10

15

20

25

30

35

Various methods are known for the production of urea granules. In the past, the predominant method was prilling, in which a substantially anhydrous urea melt is sprayed from the top of a prilling column into a rising stream of air of ambient temperature in which the droplets solidify to form so-called prills. These prills have a relatively small maximum diameter and are mechanically rather weak.

Nowadays, urea granules having larger dimensions and better mechanical properties are produced by granulating a substantially anhydrous urea melt or of an aqueous urea solution in a fluidized bed, for instance as described in US-4.619.843.

In this patent publication a process is described for the preparation of granules in a fluidized bed process by feeding a urea melt to a fluidized bed of solid urea nuclei, upon which the nuclei grow by solidification of the urea melt on the nuclei. The process is suitable not only for the preparation of urea granules, but also for the granulation of other materials such as sulphur and ammonium nitrate. In the fluidized bed feeding devices are used comprising a central channel from where the liquid material is supplied as a virtually closed, conical film and a channel concentric therewith through which a gas stream is supplied. The main advantage of this process is that it is low in energy consumption.

Besides urea, the urea melt that is fed to the fluidized bed contains water. The urea melt can, for instance, be obtained by concentrating an aqueous urea containing stream coming from a urea plant. This concentration takes place at high temperatures and/or low pressures. The concentrating conditions stimulate the formation of biuret. Biuret is an organic by-product that can be obtained during urea production. It has no adverse effects on human health or the environment. During fluid-bed granulation the weight % of biuret always shows a minor increase. The water present in the urea melt evaporates to a large extent during fluid-bed granulation of urea.

The presence of water in the urea melt used for fluid-bed granulation has some very important advantages.

First, concentration of the urea melt in an evaporator before feeding it to the fluidized bed is simpler and less energy consuming when some water is left in

the urea melt. Second, the evaporation of the water in the fluidized bed improves the heat balance, so that less fluidizing air is needed for cooling. As a result thereof a smaller scrubbing section is needed to clean the fluidizing air.

The main disadvantage of the presence of water in the urea melt is

the high concentration of granulation additives that needs to be present in the urea melt to be able to form urea granules out of the melt in a fluid-bed granulator.

Granulation additives are expensive and hazardous to health and the environment.

Examples of granulation additives used in urea granulation are formaldehyde, methylolurea, formurea and hexamethylenetetramine. The granulation additives are added to reduce dust formation during granulation, to obtain urea granules with satisfactory mechanical properties and to obtain free-flowing urea granules.

The present invention is based on extensive investigations aimed at reducing the concentration of granulation additives during granulation while at the same time maintaining or even improving the mechanical properties, such as crushing strength and caking tendency, and the free-flowing properties of the granules. Another aim was to reduce dust formation.

It has now surprisingly discovered that when during fluid-bed granulation the amounts of biuret and water in the urea melt and in the urea granules fulfill the following relation

$$\frac{b_{m} \cdot b_{g}}{w_{m} \cdot (w_{m} - w_{g})} = 0.1-20$$
wherein

15

25

30

35

 b_m = the % by weight of biuret in the urea melt b_g = the % by weight of biuret in the urea granules w_m = the % by weight of water in the urea melt w_g = the % by weight of water in the urea granules;

the required concentration of granulation additives can be greatly reduced. Granulation additives can even be absent during granulation.

During fluid-bed granulation the value of the above-mentioned relation is 0.1-20, preferably 0.1-10, most preferably 0.2-5. When the value of the above-mentioned relation is below 0.1 a large concentration of granulation additives is always necessary and a value of the relation above 20 leads to unacceptable high costs for energy consumption related to the evaporation section and/or to increased ammonia emission.

The amounts of water and biuret in the urea melt can be obtained by

a large number of different methods. Examples of these methods are given below.

The amounts (given as weight percentages) of water and biuret in the urea melt can be obtained in and/or downstream of one or more evaporator(s) that are placed upstream of the feeding device. Preferably, two evaporators in series are used. All kinds of commercially available evaporators can be used; for instance VOP-type evaporators. Also, between the evaporator and the feeding device water, a water-rich urea solution or a biuret-rich stream can be added to the urea melt to influence the weight percentages of water and biuret in the urea melt.

5

10

15

20

25

30

35

The weight percentages of water and biuret in the urea melt can also be obtained in a vessel that is present between the evaporator and the feeding device. Biuret can be obtained in the urea melt when the temperature of the melt is higher than 130 °C. The vessel can be kept at a temperature above 130 °C and the residence time of the urea melt can be chosen in such a way that a urea melt is obtained with the desired weight % of biuret.

The weight percentages of water and biuret in the urea melt between the evaporator and the feeding device can also be obtained in other ways, for instance by heating the piping used to feed the urea melt to the feeding device.

Preferably, the weight percentages of water and biuret in the urea melt are obtained by using two evaporators arranged in series, wherein part of the urea melt leaving the first evaporator being fed to the second evaporator and part of the urea melt leaving the first evaporator being combined with the urea melt leaving the second evaporator. This has the advantage that the amounts of biuret and water in the urea melt can be changed easily by varying the part of urea melt that flows from the first evaporator to the second evaporator.

The feeding device delivers the urea melt in the form of a film to a fluidized bed of solid urea nuclei, upon which the nuclei grow by solidification of the urea melt on the nuclei. The urea melt has to be fed to the fluidized bed in the form of a film in order to prevent dust formation. In principle, the film can have all kinds of configurations, but a virtually closed conical film is preferred.

The urea melt is introduced into the fluidized bed of nuclei from the bottom upwards with the aid of at least one feeding device provided with a central channel through which the urea melt is supplied and a channel concentric therewith through which a gas stream is supplied with a linear upward velocity higher than that of the fluidization gas. The gas stream creates a rarefied zone in the bed above the feeding device. After exiting the central channel the urea melt enters the rarefied zone.

Before hitting the film, the gas stream sucks nuclei from the bed, entrains them and is thereby slowed down, so that both the film and the gas stream are deflected upon impact, and the entrained nuclei penetrate the film and are thereby moistened with a small amount of urea melt, which subsequently, in the rarefied zone, can solidify to such an extent that after exiting the rarefied zone the particles are sufficiently dry to prevent agglomeration.

5

10

15

20

25

30

35

A closed conical film can, in principle, be obtained in various ways. For example, the urea melt can be converted to a film with the aid of a tapered part at the end of the outlet channel. Preferably, the conical film is obtained by imparting a rotation to the urea melt. Of course, besides the rotational speed imparted to the material, the hydrostatic pressure on the urea melt is also important. In general, the urea melt is supplied under a hydrostatic pressure of 0.15 to 0.60 MPa, in particular 0.18 to 0.40 MPa. By preference, a feeding device provided with a rotation chamber is used.

It has been found that to obtain a smooth surface of the film the melt velocity should in general be at most 30 m/sec and preferably 10-25 m/sec.

The gas stream takes up nuclei and is thereby slowed down before hitting the film. This is preferably achieved by making the gas channel lead into the fluidized bed in a place lower than the central channel. In this way, the gas stream can entrain nuclei along some distance and impart a certain velocity to them before they hit the film. This so-called free distance can vary within wide limits, for example 0.5-5.0 cm. Preferably, a free distance of 1-4 cm is used.

In the present process, air is preferably used as the gas stream and is supplied with a velocity of at least 50 m/sec, in particular 50-400 m/sec, in general under a feed pressure of 0.11 to 0.74 MPa. The temperature of this gas stream can vary. In general, a gas stream is used which has a temperature that is about equal to that of the urea melt. The required amount of this gas stream is exceptionally low in the present invention. In general, a weight ratio of gas to urea melt of between 0.1 and 0.8, in particular between 0.2 and 0.6, is applied.

After exiting from the gas channel, the gas stream sucks nuclei from the bed and entrains them. The velocity of the gas stream thereby decreases, while the nuclei acquire a certain velocity, for example 0.1-10 m/sec.

When the film and the gas stream make impact, the nuclei entrained in the gas stream fly almost straight ahead, that is, through the film, on account of their mass. These nuclei are thereby moistened with a thin layer of urea melt, which

WO 2005/049193

5

10

15

20

25

30

35

completely or almost completely solidifies in the rarefied zone. The amount of urea melt taken up depends on, among other things, the film thickness and the particle diameter.

The gas stream not only transports particles but also serves to create the rarefied zone above the feeding device. This zone should be of sufficient height to allow the urea melt on the particles to solidify to a sufficient extent, for example about 30 cm, but on the other hand the surface of the bed should be prevented from breaking locally, in view of the risk of dust emission. These conditions are determined by the mass and velocity of the gas stream and the height of the bed, which is, for example, 40-100 cm.

As nuclei in the fluidized bed, in principle all kinds of pellets can be used, for example prills separately prepared from a portion of the urea melt to be sprayed, or from a melt obtained by melting the oversize fraction obtained after screening of the granulate. Preferably, as nuclei, granules are used which have been obtained during screening and/or crushing of a small portion of the granulate obtained from the bed. The average diameter of these nuclei may vary, partly depending on the nature of the material to be granulated and especially on the desired particle size of the product. The quantity of nuclei introduced may also vary.

The bed of nuclei is kept in a fluidized state by an upward-flowing gas, in particular air. This fluidization gas should have a minimum superficial velocity to ensure that the entire bed is kept in a fluidized state. On the other hand, this velocity should not be too high to prevent emission of urea fines.

The invention will be explained in detail with reference to the accompanying figures.

In Figures 1 to 5 different processes for the preparation of urea granules according to the invention are shown.

Figures D1-D3 are included as possible places for metering devices of granulation additives.

Figure 1 U represents the urea process in which the urea melt was obtained. In this urea melt b_m was 0.4 wt% and w_m was 20 wt%. The urea melt was led to the evaporator (E1) to obtain a b_m of 0.7 wt% and a w_m of 5 wt% and thereafter to the evaporator (E2) to obtain a b_m of 0.9 wt% and a w_m of 1.3 wt%. After the evaporator the urea melt was led to the spraying devices (S) in the granulator (G). In the spraying devices the urea melt was sprayed together with the air stream (A). Fluidizing air was also fed to the granulator. Granules with a b_g of 0.92 wt% and a w_g of 0.1 wt% were obtained. The value of the quotient in the above-mentioned relation was 0.53.

In Figure 2 a process for the preparation of urea granules was presented according to Figure 1. A urea melt with a b_m of 0.4 wt% and a w_m of 20 wt% was led to the first evaporator. The urea melt that leaves the first evaporator had a b_m of 0.7 wt% and a w_m of 5 wt% and 75% of it was led to the second evaporator. After the second evaporator a stream with a b_m of 0.9 wt% and a w_m of 1.3 wt% was obtained. This stream of urea melt was combined with the rest of the urea melt leaving the first evaporator, resulting in a urea melt with a b_m of 0.85 wt% and a w_m of 2.2 wt%, which was led to the spraying devices. Granules with a b_g of 0.88 wt% and a w_g of 0.3 wt% were obtained. The value of the quotient in the above-mentioned relation was 0.18.

5

10

15

20

25

30

35

Figure 3 represents a process for the preparation of urea granules according to Figure 1 in which after the evaporator a vessel (V) was placed for further treatment of the urea melt. The urea melt that enters the evaporator had a b_m of 0.4 wt% and a w_m of 20 wt%. After the evaporator a urea melt was obtained with a b_m of 0.7 wt% and a w_m of 2 wt%. In the vessel the urea melt was kept at a temperature of 135 °C for 10 minutes, after which it was led to the spraying devices. The b_m and w_m values in the urea melt that was sprayed were 1.2 wt% and 2 wt%, respectively. Granules with a b_g of 1.3 wt% and a w_g of 0.3 wt% were obtained. The value of the quotient in the above-mentioned relation was 0.42.

Figure 4 shows a process for the preparation of urea granules according to Figure 1 in which after the evaporator a heating device (H) was placed for further treatment of the urea melt. The weight % of biuret and water in the urea melt that entered the evaporator are 0.4 and 20, respectively. After the evaporator a urea melt was obtained with a b_m of 0.9 wt% and a w_m of 1.0 wt%. In the heating device the urea melt was kept at a temperature of 150 °C for 1 minute, after which it was led to the spraying devices. The b_m and w_m values in the urea melt that was sprayed are 2.5 wt% and 1.0 wt%, respectively. Granules with a b_g of 2.6 wt% and a w_g of 0.1 wt% were obtained. The value of the quotient in the above-mentioned relation was 7.2.

Figure 5 shows a process for the preparation of urea granules according to Figure 1 in which after the evaporator a heating device (H) and a cooler (C) were placed for further treatment of the urea melt. The weight % of biuret and water in the urea melt that enters the evaporator were 0.4 and 20, respectively. After the evaporator a urea melt with a b_m of 0.8 wt% and a w_m of 1.5 wt% was obtained. In the heating device the urea melt was kept at a temperature of 160 °C for 30 seconds, after which it was led to the cooler. In the cooler the urea melt was kept at a temperature of 135 °C for 10 seconds, after which it was led to the spraying devices. In the urea melt

WO 2005/049193

that was sprayed b_m was 2.2 wt% and w_m was 1.5 wt%. Granules with a b_g of 2.3 wt% and a w_g of 0.2 wt% were obtained. The value of the quotient in the above-mentioned relation was 2.59.

PCT/EP2004/011678

5 Examples

The mechanical properties of the granulate produced in the granulator are characterized by a number of quality parameters.

One such quality parameter is the crushing strength of a granule, defined as the

pressure at which a granule breaks down into fine particles. The crushing strength of a granule is of importance in the handling and storage of the urea product between the manufacturer's plant and the end user. In order to assure that the product conforms to user expectations (such as easy handling, good spread-ability, low/no losses in the application) at the end-user, too, the crushing strength of the granulate as produced in the manufacturer's plant should be more than 2 MPa, and preferably more than 3 MPa. It has now been found that the crushing strength of the produced granulate can be influenced by modifying the parameters in the above-mentioned relation. At a value of the above-mentioned relation above 0.1 granulate with a good crushing strength can be obtained with considerably lower, or even no, metering of the above-mentioned granulation additives.

20

25

30

35

15

10

Example A:

A fluid bed granulator including a feeding device that fed the urea melt in the form of a virtually closed conical film was used in a process set-up as shown in Fig 1. A urea melt having a b_m of 0.9 wt% and a w_m of 1.3 wt% was supplied to this feeding device. The values for the b_g en w_g in the granules were 0.92 wt% and 0.1 wt%. The value of the relation was 0.52. Without any formaldehyde having been metered, the crushing strength of the urea granules produced had an acceptable value of 3.0 MPa. After metering of 0.2 wt% of formaldehyde (relative to the total amount of melt supplied to the feeding device), the crushing strength of the urea granules increased to 4.2 MPa.

Comparative Experiment 1:

Urea granules were prepared according to the same process as described in Example A.

Using only evaporator E1 for the treatment of the urea melt, a urea

melt with a b_m of 0.7 wt% and a w_m of 5.0 wt% was supplied to the feeding device. Granules were obtained with a b_g of 0.7 wt% and a w_g of 1.0 wt%. The value of the relation was 0.024. 0.5 wt% of formaldehyde (relative to the total melt supply to the feeding device) was added via metering device D1. Urea granules with an unacceptable crushing strength of 0.7 MPa were obtained. When the metering of formaldehyde was stopped, the crushing strength of the urea granules dropped to the even lower value of 0.5 MPa.

5

10

15

20

25

30

35

Another important mechanical property of the granulate produced is its caking tendency. A non-caking, free flowing product is of importance to ensure easy handling and minimum spillage of the product during transport, as well as at its final application. The most common final application of urea is fertilizer. In most countries, fertilizer is nowadays spread over the land by rolling mechanical devices. It is very important that in these mechanical devices the urea is free flowing and is free of lumps. Lumps in, or non-free flowing behavior of the urea granulate, would result in uneven distribution of the fertilizer over the land, with a negative influence on the crop-yield in those land area's where a lower than average dosing of fertilizer is applied. The caking tendency of urea can, for example, be measured in a test in which a sample of the granulate is stored for a certain time under a specified pressure. The pressure that is required to break the sample after this storage is a measure of the caking tendency of the granulate. The higher this breaking pressure, the higher the caking tendency of the product. In general, the caking tendency should be lower than 0.8 bar in order to ensure that the application of the fertilizer at the end-user will be trouble free.

It is well known that the caking tendency of urea granulate can be reduced by adding granulation additives. It is also known that the caking tendency of urea granulate can be reduced by covering the surface of the granulate with surface-active components. For this purpose sometimes aqueous solutions of a saponifier (such as alkyl sulphonate or alkyl sulphate) are sprayed over the surface of the urea granulate. A disadvantage of this kind of surface protection of the granulate is the high cost of these additives.

It has now been found that the caking tendency of urea granulate can also be influenced by the value of the above-defined relation between the values of biuret and water. By choosing the right values for biuret and water a granular product with good to excellent non-caking behavior can be obtained without metering the

above-mentioned additives, or with greatly reduced quantities of additives.

Example B:

5

10

20

25

30

A fluid bed granulator, that included, applying a feeding device that fed the urea melt in the form of a virtually closed conical film was used in a process set up as given in Fig 5. With this feeding arrangement a urea melt with a b_m of 2.2 wt% and a w_m of 1.5 wt% could be obtained. In the granules the b_g was 2.3 wt% and the w_g was 0.2 wt%. The value of the relation was 2.59. The caking tendency of the urea granules had an acceptable value (0.4 bar). After adding only 0.05% of an aqueous solution of ethyl-hexyl sulphate via dosing device D3, the caking tendency of the urea granules had an excellent value of <0.1 bar. In this way the handling of a toxic formaldehyde solution could be avoided, whilst the cost of the expensive ethyl-hexyl sulphate metering was halved compared to comparative experiment 2.

15 Comparative Experiment 2:

The evaporation section between the urea plant and the feeding device to the granulator was modified in the way illustrated in Fig 1 with only one evaporator. A urea melt having a b_m of 0.7 wt% and a w_m of 5.0 wt% was supplied to this feeding device. The values of b_g and w_g were respectively 0.7 wt% and 1.0 wt%.

The value of the relation was 0.024.

0.5 wt% of formaldehyde (relative to the total melt supply to the feeding device) was added via metering device D1. 0.1 wt% (relative to the total melt supplied to the feeding device) of an aqueous solution of ethyl-hexyl sulfate was added to the granulate via metering device D3. Urea granules with a good non-caking behavior were obtained (caking tendency < 0.1 bar). When the metering of formaldehyde and of ethyl-hexyl sulphate was stopped, the caking tendency of the urea granules appeared to be fully unacceptable (caking tendency 2 bar).